

Release notes TWFS2

These release notes are applicable to the following modules:

- ASI10

Software version 1623
Hardware version 0200
Platform TWFS2
Date 27-07-2015
Filename ASI10-0200-1623-service.zip

- Solved the backup switch from accidentally getting stuck. A specific datalink corruption causes switch away from affected input without reporting ASI Link alarm. This condition persisted until cleared by subsequent TS Stopped or TS Sync Loss on the affected input.
- Solved stuck packet separation measurement value when input is lost.
- Changed ASI-Link-Det, TS-Stopped-Det and TS-SyncLoss-Det to be set to only A+B mandatory.

Software version 1520
Hardware version 0200
Platform TWFS2
Date 12-12-2014
Filename ASI10-0200-1520-service.zip

- Corrected failure that appeared in version 1120, sometimes the switch was actually not in Auto mode when it was configured to be in Auto mode.

Software version 1120
Hardware version 0200
Platform TWFS2
Date 14-11-2012
Filename ASI10-0200-1120-service.zip

- Added Combined mode Output-Config.

Software version 1020
Hardware version 0200
Platform TWFS2
Date 23-10-2012
Filename ASI10-0200-1020-service.zip

- Changed Switch-Back=Off behavior. Stay switched regardless if input A returns ok.
- Fixed 2x1 Switch-Back=BackUp_Fail to remain switched to input B when A returns to ok.

Software version 0920
Hardware version 0200
Platform TWFS2
Date 30-01-2012
Filename ASI10-0200-0920-service.zip

- Fixed 2x1 Switch-Back=On behavior.
 - Simplified the 2x1 settings to one 2x1 setting, like the 2IX SDI cards.
-

Software version 0820
Hardware version 0200
Platform TWFS2
Date 01-09-2011
Filename ASI10-0200-0820-service.zip

- Solved loss of input B on specific boards.
-

Software version 0812
Hardware version 0200
Platform TWFS2
Date 06-01-2011
Filename ASI10-0200-0812-service.zip

- First release.
-