

Release notes SYLA1,SYLA2

These release notes are applicable to the following modules:

- DDP94

Software version 0506
Hardware version 0100, 0101, 0102, 0200
Platform SYLA1,SYLA2
Date 23-11-2015
Filename DDP94-0100to0200-0506-service.zip

- added pcm delay for backup channel

Software version 0405
Hardware version 0100, 0101, 0102, 0200
Platform SYLA1,SYLA2
Date 23-05-2013
Filename DDP94-0100to0200-0405-service.zip

- changed quadspeed input bus location

Software version 0404
Hardware version 0100, 0101, 0102, 0200
Platform SYLA1,SYLA2
Date 21-05-2013
Filename DDP94-0100to0200-0404-service.zip

- changed quadspeed mux position. solved bug 2254
- intended to use with dolby version 2407
- rev mode for metadata is default last valid.

Software version 0403
Hardware version 0100, 0101, 0102, 0200
Platform SYLA1,SYLA2
Date 18-01-2013
Filename DDP94-0100to0200-0403-service.zip

- transcoding startup
- fixed datarate 7.1
- intended to use with version 2407

Software version 0303
Hardware version 0100, 0101, 0102, 0200
Platform SYLA1,SYLA2
Date 26-06-2012
Filename DDP94-0100to0200-0303-service.zip

- Datarate issue HE-AAC solved
- intended to use with version 2403
- added warble tone mixing
- added AD mixing

Software version 0202
Hardware version 0100, 0101, 0102, 0200
Platform SYLA1,SYLA2
Date 11-1-2012
Filename DDP94-0100to0200-0202-service.zip

- Added support for DD and DDplus combined
- intended to use with version 2232

Software version 0102
Hardware version 0100, 0200, 0200
Platform SYLA1,SYLA2
Date 1-11-2011
Filename DDP94-0100to0200-0102-service.zip

- initial release
 - intended to use with version 2232
-