

# Release notes SYHDV1-SYHDV1,SYHDV2-SYHDV2

These release notes are applicable to the following modules:

- GDV090

---

**Software version** 1010  
**Hardware version** 0102, 0103, 0104, 0105  
**Platform** SYHDV1,SYHDV2  
**Date** 12-11-2014  
**Filename** GDV090-0102to0105-1010-service.zip

Merged firmware for hardware version 0102 to 0104 with firmware for hardware version 0105  
No functionality changes with reference to firmware version 0910

---

**Software version** 0910  
**Hardware version** 0105  
**Platform** SYHDV2  
**Date** 16-10-2014  
**Filename** GDV090-0105-0910-service.zip

bug fix y/c delay

---

**Software version** 0809  
**Hardware version** 0105  
**Platform** SYHDV2  
**Date** 19-07-2013  
**Filename** GDV090-0105-0809-service.zip

Firmware update due to hardware redesign (replaced obsolete CVBS encoder)

---

**Software version** 0709  
**Hardware version** 0102, 0103, 0104  
**Platform** SYHDV1,SYHDV2  
**Date** 25-02-2013  
**Filename** GDV090-0102to0104-0709-service.zip

- Solved bug spikes in video

---

**Software version** 0708  
**Hardware version** 0102, 0103, 0104  
**Platform** SYHDV1,SYHDV2  
**Date** 20-12-2012  
**Filename** GDV090-0102to0104-0708-service.zip

- Added constant 40ms delay option  
- pan pix to right so no blue line in active video

---

**Software version** 0607  
**Hardware version** 0102, 0103, 0104  
**Platform** SYHDV1,SYHDV2  
**Date** 21-05-2012  
**Filename** GDV090-0102to0104-0607-service.zip

- 16 channels audio to bus

---

**Software version** 0506  
**Hardware version** 0102, 0103, 0104  
**Platform** SYHDV1,SYHDV2  
**Date** 17-01-2012  
**Filename** GDV090-0102to0104-0506-service.zip

- Fixed instable detection of SD signals  
- Improved internal stability

---

**Software version** 0405  
**Hardware version** 0102, 0103, 0104  
**Platform** SYHDV1,SYHDV2  
**Date** 13-12-2011  
**Filename** GDV090-0102to0104-0405-service.zip

- Added Level-B support (only for ADD9490710011)  
- Added PAL-M support

---

**Software version** 0203  
**Hardware version** 0102, 0103  
**Platform** SYHDV1  
**Date** 6-5-2010  
**Filename** GDV090-0102to0103-0203-service.spf

- all known bugs

**Software version** 0202  
**Hardware version** 0102  
**Platform** SYHDV1  
**Date** 2-2-2010  
**Filename** GDV090-0102-0202-service.spf

- on AES output 1/2 the Left and right are swapped.

---